

IF THE PAGE FILMED IS NOT  
AS LEGIBLE AS THIS LABEL,  
IT IS DUE TO THE QUALITY  
OF THE ORIGINAL.

EPA POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION		REGION	SITE NUMBER
		06	LAD 981910664
NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.			
A. SITE NAME Michel T. Halbouty <i>More Lease</i>		B. STREET (or other identifier) South of LA Hwy 390, 0.75 mi. West of LA Hwy 27	
C. CITY Hackberry	D. STATE LA	E. ZIP CODE 70643	F. COUNTY NAME Cameron 623
G. OWNER/OPERATOR (if known) L. NAME Chevron, USA, Inc. P.O. BOX 285, Houston, TX 77001			2. TELEPHONE NUMBER
H. TYPE OF OWNERSHIP (if known) <input type="checkbox"/> 1. FEDERAL <input type="checkbox"/> 2. STATE <input type="checkbox"/> 3. COUNTY <input type="checkbox"/> 4. MUNICIPAL <input checked="" type="checkbox"/> 5. PRIVATE <input type="checkbox"/> 6. UNKNOWN			
I. SITE DESCRIPTION 29°59'02"N 93°22'56"W 0.5 acre site is an active petroleum production and separation facility which has several oil wells, separators, and storage tanks, and an 11' X 12' desalinization pit. See "CAM 55", Browns Lake topo map.			
J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.) Aerial photographs and FIT windshield survey			K. DATE IDENTIFIED (mo., day, & yr.) 2-17-87
L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM The pit contains two rusted 55 gallon drums and black oily water with bubbles on the surface. Poor containment is evidenced by the leaking of oily water beneath the dike and by the oily sludge on the ground outside of the pit. Diking surrounding the tanks and separators is also inadequate to prevent oily sludge and salt water from leaving the site.  <i>Lad 981910664</i>			
SUPERFUND FILE  JUL 20 1992  REORGANIZED			
Review by GHS Date <i>2/22/92</i>			
M. PREPARER INFORMATION 1. NAME R. David Shiels/JoAnn T. Weber <i>R. David Shiels</i> <i>JoAnn T. Weber</i>		2. TELEPHONE NUMBER (214) 742-6601	3. DATE (mo., day, & yr.) 2-24-87

IF THE PAGE FILMED IS NOT  
AS LEGIBLE AS THIS LABEL,  
IT IS DUE TO THE QUALITY  
OF THE ORIGINAL.

BROWNS LAKE QUADRANGLE  
LOUISIANA-CAMERON PARISH  
7.5 MINUTE SERIES ORTHOPHOTOMAP (TOPOGRAPHIC)

NW 4 CAMERON 15 QUADRANGLE

